



Simple measurement of the glove size needed

Hold your hand out flat and measure the circumference of your hand above the base of the thumb with a tape measure as shown in the illustration on the left.

The measured value will give you an indication which glove size is suitable for you:

Size S = circumference 18 cm – 21 cm (7 inch – 8.2 inch)

Size M = circumference 21 cm – 24 cm (8.3 inch – 9.4 inch)

Size L = circumference 24 cm – 27 cm (9.5 inch – 10.6 inch)

Size XL = circumference 27 cm – 29 cm (10.7 inch – 11.4 inch)



www.tipstim.com